

MODEL

44

44 S

WHEELCO INSTRUCTION MANUAL

MP MASTER

MA32119

BARBER COLMAN

BARBER-COLMAN COMPANY

Wheelco Instruments Division | ROCKFORD, ILLINOIS, U. S. A.

EXTERNAL WIRING DIAGRAM SHOWING MODEL 44 6-POINT SWITCH USED WITH AN INDICATING PYROMETER



wheelco instruments division
BARBER-COLMAN COMPANY • ROCKFORD, ILLINOIS, U. S. A.
Instrumentality
F 6039
Litho in U.S.A.

Mounting Dimensions For Wheelco Indicating Pyrometers and Resistance Thermometers

MODEL 141P AND INDICATING UNIT FOR MODELS 5122, 5822 AND 5842



SWITCHES MODELS 810, 810S, 811, 820 AND 821

STANDARDIZING UNIT MODELS 875, 885 AND 895 (ALSO USED FOR MODELS 5122, 5822 AND 5842)

MODELS 43, 44 AND 44S



MOUNTING DIMENSIONS FOR INDICATING PYROMETER MODEL 192



DETAIL OF PANEL CUT-OUT FOR FLUSH MOUNTING



TOP VIEW OF SURFACE MOUNTING CASE

SIDE VIEW

BARBER COLMAN **Wheelco Instruments Division** | **BARBER-COLMAN COMPANY**
ROCKFORD, ILLINOIS, U. S. A.

MP MASTER
MA32119

F-5328-10

Printed in U. S. A.